

I N S T R U C T I O N B O O K
f o r
U N I V E R S A L M I L L I N G M A C H I N E T Y P E F 1

Machine No.: 37.949

Operating Voltage - Motor: 420 V.

Operating Voltage - Lighting and Controls:

Driving Belt Dimensions: 10 x 410

Name of Client: Messrs. Adam Machine Equipment Ltd, Harpenden.

Date supplied: 8.6.1971

A C I E R A S A - M a c h i n e T o o l M a n u f a c t u r e r s
L E L O C L E - (S w i t z e r l a n d)

<u>FABRICANT / HERSTELLER / MAKER</u>		<u>TYPE / TYP</u>	01-96-0014-01
b1-b2	Weber, Emmenbrücke/Lucerne (CH)	ME 10/30	Liste des appareils électriques
b3	Weber, Emmenbrücke/Lucerne (CH)	SE 10/40	
b4	Feller AG, Horgen/Zürich (CH)	7730/61	
b5	Feller AG, Horgen/Zürich (CH)	8714 BT 60 3P+T	
	Tschudin et Heid, Reinach (CH)	Buser 1104V 3P+T	
e1	Weber, Emmenbrücke/Lucerne (CH)	1720 E + KII + SII + DTII 4A	Elektrische Geräte Liste
e2	Weber, Emmenbrücke/Lucerne (CH)	1720 E + KII + SII + DII 2A	
e3	Schürter, Lucerne (CH)	704 M + 709 + Sp 2.5A	
h1	Rütti, Bienne (CH)	F1 culot B15	List of electrical components
	Osram, Zürich (CH)	B15 24V 25W Ø 45	
L1	Wcoertz, Bâle (CH)	4001 J + 4001 Jgg	
m1	Marelli, Milan (I)	PMU 100 A1 B2	
m2	Golay-Buchel, Lausanne (CH)	MEV 2 1/3 CV	
m3	Sormani, Magliaso/Tessin (CH)	A 35 35 VA	

<u>MOTEURS / MOTOREN / MOTORS</u>		220 V	380 V	500 V	
m1	Pompe	T/min			Caract. électriques
	Pumpe	2750 U/min	80W . 0.5A	0.3A . 0.18A	
	Pump	RPM			
m2	Broche	T/min	CV		Elektrische Daten
	Spindel	2860 U/min	1/3 PS 0.94A	0.55A 0.40A	
	Spindle	RPM	HP		

<u>INTERRUPTEURS-DISJONCTEURS / MOTORSCHALTER / MOTOR SWITCH</u>				Electrical Charact.
	Réglable - Einstellbereich	Réglé - Eingestellt		
	Adjustable	Adjusted		
b1	Pompe - Pumpe - Pump			
	220 V	0.35-0.52A	0.5A	
	380 V	0.25-0.38A	0.3A	
	500 V	0.18-0.26A	0.18A	
b2	Broche - Spindel - Spindle			
	220 V	0.70-1.05A	0.94A	
	380 V	0.50-0.75A	0.55A	
	500 V	0.35-0.52A	0.40A	




b1-b2	Interrupteurs disjoncteurs	b1	Pompe d'arrosage m1
		b2	Moteur broche m2
b3	Inverseur		Moteur broche m2
b4	Interrupteur lumière		Eclairage
b5	Prise et fiche		Moteur broche m2
e1-e2	Fusibles principaux	e1	Entrée force
		e2	Entrée transformateur
e3	Fusible du secondaire		Circuit d'éclairage 24V
h1	Lampe		Eclairage
L1	Groupe de bornes		Entrée du courant
m1-m2	Moteurs	m1	Pompe d'arrosage
		m2	Moteur broche
m3	Transformateur		Eclairage


b1-b2	Motorschalter	b1	Kühlmittelpumpe m1
		b2	Spindelmotor m2
b3	Drehrichtungsschalter		Spindelmotor m2
b4	Lichtschalter		Beleuchtung
b5	Steckdose und Stecker		Spindelmotor m2
e1-e2	Hauptsicherungen	e1	Starkstromeingang
		e2	Transformatoreingang
e3	Sicherung für Steuerung		Beleuchtung 24V
h1	Lampe		Beleuchtung
L1	Klemmenleiste		Stromeingang
m1-m2	Motoren	m1	Kühlmittelpumpe
		m2	Spindelmotor
m3	Transformator		Beleuchtung

b1-b2	Motor switches	b1	Coolant pump motor m1
		b2	Spindle motor m2
b3	Reversing switch		Spindle motor m2
b4	Switch for light		Lighting
b5	Socket and plug		Spindle motor m2
e1-e2	Main fuses	e1	Input power
		e2	Input transformer
e3	Fuse for control circuit		Lighting circuit 24V
h1	Lamp		Lighting
L1	Connection terminals		Input main terminals
m1-m2	Motors	m1	Coolant pump motor
		m2	Spindle motor
m3	Transformer		Lighting



01-07-0014-01





ALIERA

KF 1

FORCE ET LUMIERE

Dessiné *R. H. J. van*
Date 1.XI.68

01-99-0014-01

4 x 15mm²












TEST CHART FOR UNIVERSAL MILLING MACHINE

FABRIQUE DE MACHINES
LE LOCLE-SUISSE

Machine Type : KF1 Order N° : AME 70618
 Machine N° : 37949
 Customer : Messrs. Adam Machine Equipment Ltd,
Harpenden.

N°	Description of Measurement	Tolerance Permissible	Error Measured	Picture
	<u>Quill spindle</u>			
1	Eccentricity of internal taper	.0002 0,005	0,004	
2	Axial play	.0002 0,005	0,005	
3	Radial play	.0002 0,005	0,003	
4	Spindle nose untrue	.0002 0,005	0,005	
5	Eccentricity measured at the end of a mandrel 100 mm long	.0006 0,015	0,010	
6	Spindle parallel to transverse movement over 75 mm measured on the mandrel	.0004 0,010	0,005	
7	measured on the mandrel side	.0004 0,010	0,007	
8	Spindle parallel to the table, measured under the mandrel x 75 mm (table high at front only)	.0004 0,010	0,006	
9	Spindle square with the longitudinal slide, x 150 mm	.0004 0,010	0,007	
10	<u>Longitudinal slide</u> Front face parallel to the longitudinal slide, x 100 mm	.0002 0,005	0,004	
11	Front face parallel to the vertical slide, x 85 mm	.0002 0,005	0,003	
12	Top face parallel to the longitudinal slide, x 100 mm	.0002 0,005	0,004	
	<u>Vertical slide:</u> square with the table:			
13	measured on the rear face of a cylinder, x 100 mm	.0004 0,010	0,005	
14	measured on the side of a cylinder, x 100 mm	.0004 0,010	0,005	

N°	Description of Measurement	Tolerance Permissible	Error Measured	Picture
	<u>Overhanging Arm Centre</u>			
15	Bore concentric with cutter spindle, x 100 mm	.0008 0,020	0,010	
	<u>Work Table</u>			
	plein * universal **			
16	Parallel to transverse movement (table high at front), x 75 mm	.0002 0,005	0,005	
		** .0002 0,005	---	
17	Parallel to longitudinal slide, x 100 mm	* .0004 0,010	0,005	
		** .0004 0,010	---	
18	Tee-slots parallel to longitudinal slide, x 100 mm	* .0004 0,010	0,006	
		** .0004 0,010	---	
19	Tee-slots square with cutter spindle, x 100 mm	* .0004 0,010	0,007	
		** .0004 0,010	---	
	<u>Vertical support</u>			
20	Bore square with the table A-A, x 100 mm	.0008 0,020	---	
21	Bore square with the table B-B, x 100 mm	.0008 0,020	---	
	<u>Swivel Support</u>			
	Bore parallel to the vertical slide:			
22	Measured behind the cylinder, x 100 mm	.0004 0,010	0,005	
23	Measured on one side of the cylinder, x 100 mm	.0004 0,010	0,005	

N°	Description of Measurement	Tolerance Permissible	Error Measured	Picture
<u>Rotary Table</u>				
24	Parallel to transverse movement, x 75 mm	.0004 0,010	0,005	
25	Parallel to longitudinal slide, x 100 mm	.0004 0,010	0,004	
26	Flatness of platform	.0004 0,010	0,004	
27	Eccentricity of bore	.0004 0,010	0,005	
<u>Dividing Head</u>				
28	Eccentricity of taper	.0002 0,005	---	
29	Axial play	.0002 0,005	---	
30	Radial play	.0002 0,005	---	
31	Eccentricity, measured at the end of an arbor, 100 mm long	.0006 0,015	---	
32	Eccentricity of tailstock centre in relation to dividing head spindle, x 100 mm	.0008 0,020	---	
<u>Vices</u>				
Rotating * Rotating and inclinable **				
33	Support face, parallel to transverse movement * **	.0004 0,010 .0004 0,010	--- --- ---	
34	Support face, parallel to longitudinal movement * **	.0004 0,010 .0004 0,010	--- --- ---	

Clamping surface	100 x 220 mm (4" x 8.5")
3 Tee-slots	8 mm (0.315")
Distance between Tee-slots	35 mm (1.38")
Distance between the table and horizontal cutter spindle axis	
minimum	10 mm (0.394")
maximum	160 mm (6.30")
Distance between the table and vertical cutter spindle nose	
minimum	10 mm (0.394")
maximum	175 mm (6.89")
Distance between the vertical cutter spindle axis and centre Tee-slot	
forwards	35 mm (1.38")
backwards	40 mm (1.58")
Displacement of the table on horizontal slide	150 mm (5.91")

No. 101
Plain
Table

Clamping surface	100 x 220 mm (4" x 8.5")
2 Tee-slots	8 mm (0.315")
Distance between Tee-slots	50 mm (1.97")
Distance between the table and horizontal cutter spindle axis	
minimum	0 mm
maximum	115 mm (4.53")
Distance between the table and vertical cutter spindle nose	
minimum	0 mm
maximum	130 mm (5.12")
Distance between the vertical cutter spindle axis and rear Tee-slot	
forwards	53 mm (2.09")
backwards	22 mm (0.87")
Displacement of the table on horizontal slide	160 mm (6.30")
Tilting to left or right	20° - 0 - 25°
Tilting backwards or forwards	30° - 0 - 30°
Swivelling (when in centre of machine column)	20° - 0 - 20°

No. 102
Universal
Table

Diameter	120 mm (4.72")
4 Tee-slots - at 90° to each other	8 mm (0.315")
Graduation	360°
Tilting each way	20° - 0 - 20°
Rotates with stops	180°
Central bore diameter	5_H6 mm

No. 103
Rotary
Table




Housing bore diameter	35 mm (1.38")	<u>No. 104</u> <u>Swivel</u> <u>Support</u>
Swivels to left and right	45° - 0 - 100°	
Distance between the support face and the horizontal cutter spindle axis		
minimum	17 mm (0.67")	
maximum	167 mm (6.58")	
Distance between the support face and the vertical cutter spindle nose		
minimum	32 mm (1.26")	
maximum	182 mm (7.17")	
Distance between the housing bore axis and the vertical cutter spindle axis		
forwards	28 mm (1.10")	
backwards	47 mm (1.85")	
Displacement of the support on the horizontal	160 mm (6.30")	
Housing bore diameter	40 mm (1.58")	<u>No. 111</u> <u>Vertical</u> <u>Support</u>
Swivels to left and right	45° - 0 - 45°	
Jaws open	55 mm (2.17")	
Breadth of jaws	60 mm (2.36")	<u>No. 121</u> <u>Swivel Vice</u>
Height of jaws	15.5 mm (0.61")	
Swivels to left and right	45° - 0 - 100°	
Rotates through	180°	
Total height (measured from support face)	46 mm (1.81")	
Jaws open	55 mm (2.17")	<u>No. 122</u> <u>Compound</u> <u>Vice</u>
Breadth of jaws	60 mm (2.36")	
Height of jaws	15.5 mm (0.61")	
Swivels to left and right	45° - 0 - 100°	
Rotates through	180°	
Tilts through	90°	
Total height (measured from support face)	84 mm (3.31")	
Housing bore diameter	35 mm (1.38")	<u>No. 123</u> <u>Simple</u> <u>Dividing</u> <u>Head with</u> <u>Swivel Body</u>
Maximum workpiece diameter with tailstock	58 mm (2.28")	
Swivels to left and right	45° - 0 - 100°	
Rotates through	180°	
Quill nose thread - diameter	22.6 mm (0.88")	
thread pitch	2 mm (0.079")	
Spindle bore and collet shank diameter	12 mm (0.47")	
Diameter of dividing plate	90 mm (3.54")	
Number of divisions (normal)	60	
Maximum distance between quill nose and tailstock centre	100 mm (3.94")	




Encom-
brement

Platzbedarf

Overall-
dimensions





D E S I G N A T I O N S

ORGANS	QUALITY	SYMBOL
General lubrication	Shell Vitrea Oil 33	○
Milling Spindle	Shell Tellus 11	□

I N S T R U C T I O N S

FREQUENCY	No.	QUANTITY
Daily	1 - 2 - 15	2 pump pushes
Weekly	4 - 6 - 7 3 - 5 - 8 - 9 10 - 11 - 13 - 14	1-2 pump pushes 2-3 pump pushes
monthly	12	1-2 pump pushes



It is best that the machine be moved to its site, by means of rollers slide underneath the base of the packing case. Remove the top and sides of the case. Take all necessary precautions to prevent damage to the machined parts and paintwork.

The bolts attaching the machine to the wooden base are accessible through the doors in the cabinet base.

It is not absolutely necessary to bolt the machine to the floor, but it should at least be level.

All the machined parts have been given a coat of rust preventative grease for protection during transport. This should be removed completely with a rag soaked in paraffin (kerosene).


Connection to the mains supply is by means of terminals located in the compartment (1) of the cabinet base. The fuses are located in the compartment (2). Insert the motor cable plug in the socket behind the machine body. Check the direction of rotation of the cutter spindle. When viewed from the front this should rotate anti-clockwise, if the machine has no reversing switch. If the machine has a reversing switch, the spindle should rotate as indicated on the control panel.

Unpacking


Erection

Cleaning


Electrical
Connections



Controls



- 3) Knob to engage or dis-engage reduction gear drive.
- 4) Screw to lock overhanging steady arm.
- 5) Screw to clamp steady centre.
- 6) Screw to clamp the quill.
- 7) Adjustable stops for the vertical slide.
- 8) Cranked handle for longitudinal table traverse.
- 9) Cranked handle for vertical table traverse
- 10) Cranked handle for transverse headstock traverse.
- 11) Adjustable stops for transverse headstock slide.
- 12) Shaft for adjustment of vertical slide compensating spring.
- 13) Screw for clamping transverse movement feedscrew nut.
- 14) Screw for clamping longitudinal movement feedscrew nut (situated behind the vertical slide).
- 15) Lever for cross traverse.
- 16) Transverse movement locking screw.
- 17) Longitudinal movement locking screw.
- 18) Adjustable stops for longitudinal slide.
- 19) Lever for longitudinal traverse.
- 20) Vertical movement locking screw.
- 21) Screw for clamping vertical movement feedscrew nut.
- 22) Lever for vertical traverse.
- 23) Coolant pump switch.
- 24) Coolant pump indicator light.
- 25) ON/OFF Switch for machine.
- 26) Switch for reversal of motor rotation.



In addition to the feedscrews, each slide is provided with adjustable levers (15 - 19 - 22) for the purpose of rapid traverse. To operate the slides by means of the levers, it is necessary to slacken off the screws (13 - 14 - 21, page DE/1) which retain the bronze feedscrew nuts in their housings. Loosen these screws (13 - 14 - 21) with the slides in the following positions:


Transverse slide:	Fully forward
Horizontal slide:	Fully to the left
Vertical slide:	Fully lowered


The bronze nuts should never be used as stops. For this purpose special stops (7 - 11 - 18, page DE/1) have been provided on each slide to limit the travel.

The levers can be repositioned by loosening the socket-screws which secure them on their shafts. The vertical slide lever is repositioned by shifting the support on the dove-tail slide.

When the levers are not being used, it is recommended that they should be removed. With regard to the vertical slide, the support on the dove-tail slide should be lifted off.

Traverse of
the slides
by lever





Play in the slides can be taken up by means of the thrust-screws (26) which bear on the tapered gibstrips. These screws are provided with lock nuts.

Play in the Slides

Adjustment of axial play in the headstock feed-screw bearing plate is effected by means of the nut (27). The grub-screw (28) ensures that this nut is firmly held onto the feed-screw. Adjustment of the vertical and longitudinal slide feed-screws is carried out in exactly the same way.

Axial play in the Feed-screws


These adjustments do not take up the play caused by wear in the bronze nuts.


With regard to the vertical feed-screw, after having adjusted the nut (27), the axial play in the feed-screw can be taken up by the nut (29). This can be reached having first removed the screw (30) and the washer (31).

Vertical Feed-screw

It is recommended not to put too much strain on the bearings.

After adjustment, replace the washer (31) and the screw (30). The latter serves to lock the nut (29).





Any play between the pinion (35) and the rack (36), can be taken up by turning the eccentric sleeve (37). This sleeve is secured by means of the screw (38).

The same system applies to the transverse (headstock) slide. The clamping screw (38) is located at the rear of the machine column.

The eccentricity of the sleeve (37) enables one to swing the pinion (35) out of the rack (36), when dismantling either the longitudinal or transverse slides.

The weight of the vertical slide is compensated for by a spiral spring, mounted inside the machine column.

The tension of this spring is adjustable.


To effect this adjustment, insert the Allen Key in the socket of the shaft (12). Push inwards as shown by the arrow, holding the key firmly to avoid a rapid unwinding of the spring when the housing (39) is freed from the retaining screw (40). Turn the key in the required direction and when the spring tension is correct, release the axial pressure so that the screw (40) engages another hole in the housing (39).

NOTE: This adjustment should be carried out when the vertical slide is in the lowest position. This will avoid undue tension on the spring.

To dismantle the compensating spring assembly, the machine must be lifted off its stand. The attaching bolts are underneath.

Adjustment
of the Lever
Feed
Mechanism

Vertical
Slide Weight
Compensating
Spring




The quill with its motor, forms an independent unit, which can be mounted horizontally directly in the bore of the headstock, or vertically in the support No. 111 designed for this purpose.

Vertical
Milling
Support

To change from the horizontal to the vertical position, one proceeds as follows:

- 1) Remove the electric plug from behind the column.
- 2) Rotate the transverse slide cranked handle into a horizontal position.
- 3) Loosen the screw (6).
- 4) Withdraw the quill.
- 5) Install the support (111).
- 6) Tighten the screw (6).
- 7) Place the quill in the bore of the support.
- 8) Tighten the screw (50) after having placed the quill at the required height.
- 9) Replace the electric plug in the socket behind the column.



Quill

1 Sealing Ring	F 1 - 4264	
1 Needle Bearing	INA	26 x 30 x 13 mm
2 Ball Bearings	6004	20 x 42 x 12 mm
2 Ball Bearings	16005	25 x 47 x 8 mm

Vertical feedscrew

2 Ball Bearings	6001	12 x 28 x 8 mm
-----------------	------	----------------

List of
Bearings
and Sealing
Rings



Radial play in the spindle (41) is adjusted by means of the nut (42). To reach this nut, proceed as follows:

Quill
Radial play

- 1) Remove the belt, motor pulley and the motor.
- 2) Remove the screws holding the plate (43) and lift out the whole sliding-gear assembly.
- 3) Remove the 4 fixing screws from the rear part of the gear-case (44).
- 4) Gently lift off the rear part and also the sliding gear (45). One is then able to remove the nut (46), having first loosened its locking screw.
- 5) Carefully withdraw the spindle (41).
- 6) As the needle bearing is mounted on a tapered ring, one screws up the nut (42) to make the necessary adjustment.


NOTE: A maximum play of 0.02 mm (.0008") can be taken up in this way. If the play still proves to be too great, it will be necessary to change the bearing and the tapered ring (48). The latter is ground on the spindle.

Axial play in the spindle (41) is adjusted by means of the nut (46). To reach this nut, proceed as follows:

Axial play

- 1) Remove the belt, motor pulley and the motor.
- 2) Remove the screws holding the plate (43) and lift out the whole sliding gear assembly.
- 3) Remove the 4 fixing screws from the rear part of the gear-case (44).
- 4) Gently lift off the rear part and also the sliding gear (45).
- 5) One is then able to reach the nut (46) and make the necessary adjustment, having first loosened its locking screw.

NOTE: The quill should not be clamped at the nose end. The adjustments of radial and axial play should only be carried by a specialist



The quill of the dividing head can be mounted directly on its support (lock screw 52), or on the swivel support No. 104.

Screw (53) blocks the arm of the tail centre.


The direct divisions are to be executed with the disc with notches (54). To change this disc, unscrew screw (55) and take it off, after having taken away the drawbar (56).

The nose (57) of the dividing head is provided with a thread dia. 22.6 x 2, which allows to adapt a chuck No. 148 or a plate No. 149.

To take up the axial and radial play of the spindle, unscrew screw (59) and adjust nut (58).

Simple
dividing
head




Axial and
radial play



Exemple
de
montage

Montage-
beispiel

Example
of
assembly



ACIERA

The Universal Dividing Attachment is an accessory which mounts on the simple dividing head.

Universal Dividing Attachment

Installation is as follows:

Installation

- 1) Remove the draw-bar (56)
- 2) Loosen the screws (55) and remove the index plate (54).
- 3) Take the universal dividing attachment and place the worm-wheel (60) on the shaft (57).
- 4) Hold up the lever (61) and push the attachment until the worm-wheel (60) butts against the nut (58) and the finger (62) engages in the notch (63).
- 5) Clamp the nut (64).
- 6) Tighten the screw (65).
- 7) Replace the draw-bar (56).

The position of the attachment can be adjusted by tightening or loosening the screw (52).

The rotation of the workpiece is via the worm (66) and the worm-wheel (60). Any play between them can be taken up by turning the sleeve (67) having first slackened off the screw (68).

Divisions

The ratio is 1 : 40 , that is to say 40 turns of the handle corresponds to 1 rotation of the workpiece.



From 0 to 50 all divisions can be made, with the exception of 47 and 49. In addition the majority of divisions between 50 and 360 can be obtained. The dividing table shows exactly all the divisions obtainable. The No. 3 Indexing Plate is provided with divisions in degrees. One turn of the handle corresponds to a rotation of the workpiece through 9°



Poupée
diviseur
univer-
selle

Univer-
sal-Teil-
apparat


Univer-
sal
dividing
head



ALIERA

To index through 17 divisions

Example of
Dividing



Look for the number 17 in the chart, in the column "Number of Divisions".

On the same line one finds in the column "Complete Turns", the figure 2, and in the column "Index Plate with 34 holes", the fraction $12/34$.

This signifies that after having made 2 turns of the index cranked handle, it is necessary to turn through a further 12 divisions on the 34 hole circle of the Index Plate No. 1.

This fraction of a turn can be controlled by means of the two sector arms.

Place the index handle between the arms, with the pin in the first hole and the first sector arm against it.

Count 12 holes round the circle, not including the first hole and, having re-inserted the pin in the 12th hole, bring the second sector arm up to it.

Do not count the hole occupied by index pin.





TABELLE DE DIVISIONS
Poupées diviseur universelle Type F3, F4
et F1

TEIL-TABELLE
Universal-Teilapparat Type F3, F4
und F1

Nombre de divisions Anzahl der Teile	Angle de rotation de la table Gradteilung	Tours entiers Voll-Umdrehung	Nombre de tours de la manivelle - Umdrehungen der Kurbel													
			fractionnaires - in Bruchteilen													
			Disque 1 - Lochscheibe 1					Disque 2 - Lochscheibe 2					Disque 3 - Lochscheibe 3			
			27	31	34	41	43	33	38	39	42	46	29	36	37	40
29	—	1									11/29					
30	12	1	9/27					11/33		13/39	14/42		12/36			
31	—	1		9/31												
32	—	1											9/36	10/40		
33	—	1						7/33								
34	—	1			6/34											
35	—	1								6/42						
36	10	1	3/27										4/36			
37	—	1												3/37		
38	—	1							2/38							
39	—	1								1/39						
40	9	1														
41	—	—				40/41										
42	—	—									40/42					
43	—	—														
44	—	—							30/33							
45	8	—	24/27										32/36			
46	—	—									40/46					
48	—	—											30/36			
50	—	—												32/40		
—	7	—	21/27										28/36			
52	—	—								30/39						
54	—	—	20/27													
55	—	—							24/33							
56	—	—									30/42					
58	—	—										20/29				
60	6	—	18/27						22/33	26/39	28/42		24/36			
62	—	—				20/31										
64	—	—												25/40		
65	—	—								24/39						
66	—	—							20/33							
68	—	—					20/34									
70	—	—									24/42					
72	5	—	15/27										20/36			
74	—	—												20/37		
76	—	—							20/38							
78	—	—								20/39						
80	—	—				17/34			19/38		21/42	23/46	18/36	20/40		
82	—	—					20/41									
84	—	—									20/42					
85	—	—				16/34										
86	—	—						20/43								
88	—	—							15/33							
90	4	—	12/27										18/36			
92	—	—									20/46					
95	—	—							16/33							



TABELLE DE DIVISIONS
 Poupée diviseur universelle Type F3, F4
 et F1

TEIL-TABELLE
 Universal-Teilapparat Type F3, F4
 und F1

Nombre de divisions Anzahl der Teile	Angle de rotation de la table Gradteilung	Tours entiers Voll-Umdrehung	Nombre de tours de la manivelle - Umdrehungen der Kurbel													
			fractionnaires - in Bruchteilen													
			Disque 1 - Lochscheibe 1					Disque 2 - Lochscheibe 2					Disque 3 - Lochscheibe 3			
			27	31	34	41	43	33	38	39	42	46	29	36	37	40
96	—	—										15/36				
100	—	—												16/40		
104	—	—						15/39								
105	—	—							16/42							
108	—	—	10/27													
110	—	—					12/33									
112	—	—							15/42							
115	—	—								16/46						
116	—	—									10/29					
120	3	—	9/27				11/33	13/39	14/42			12/36				
124	—	—		10/31												
130	—	—						12/39								
132	—	—					10/33									
135	—	—	8/27													
136	—	—		10/34												
140	—	—							12/42							
144	—	—										10/36				
145	—	—									8/29					
148	—	—											10/37			
152	—	—						10/38								
155	—	—		8/31												
156	—	—							10/39							
160	—	—										9/36		10/40		
164	—	—				10/41										
165	—	—					8/33									
168	—	—								10/42						
170	—	—			8/34											
172	—	—				10/43										
180	2	—	6/27									8/36				
184	—	—								10/46						
185	—	—											8/37			
190	—	—						8/38								
195	—	—							8/39							
200	—	—												8/40		
205	—	—				8/41										
210	—	—								8/42						
215	—	—					8/43									
216	—	—	5/27													
220	—	—						8/33								
230	—	—								8/46						
232	—	—									5/29					
240	—	—								7/42		6/36				
248	—	—		5/31												
260	—	—							6/39							
264	—	—					5/33									



POUPÉE DIVISEUR UNIVERSELLE Type F3, F4 **Universal-Teilapparat Type F3, F4**
et F1

Nombre de divisions Anzahl der Teile	Angle de rotation de la table Gradteilung	Tours entiers Volte Umdrehung	Nombre de tours de la manivelle - Umdrehungen der Kurbel												
			fractionnaires - in Bruchteilen												
			Disque 1 - Lochscheibe 1					Disque 2 - Lochscheibe 2					Disque 3 - Lochscheibe 3		
			27	31	34	41	43	33	38	39	42	46	29	36	37
272	—	—			5/34										
280	—	—								6/42					
288	—	—										5/36			
290	—	—									4/29				
296	—	—											5/37		
304	—	—							5/38						
310	—	—		4/31											
312	—	—								5/39					
320	—	—												5/40	
328	—	—				5/41									
330	—	—							4/33						
336	—	—								5/42					
340	—	—			4/34										
344	—	—												5/43	
360	1°	—	3/27										4/36		
—	54'	—												4/40	
—	40'	—	2/27												
—	30'	—										2/36			

The slotting attachment is actuated by an eccentric driver. For this reason the stroke of 10 mm (3/8") is not variable.


Slotting
Attachment


Installation

To install the attachment, proceed as follows:


- 1) Loosen off the screw (6) and slide the quill forwards until it projects 21 mm from the front of the headstock.
- 2) Tighten the screw (6).
- 3) Insert the eccentric driver in the attachment, with the ball-bearing in the slot of the slide (51).
- 4) Insert the 20 mm dia. spigot in the upper bore of the attachment with the key directed downwards.
- 5) Place the attachment in position, at the same time rotating the cutter spindle, so that the driver key-way engages with the spindle key.
- 6) Tighten the clamping screw located on the left-hand side of the attachment.
- 7) Tighten the quill draw-bar.

NOTE: Maximum driving speed 250 R.P.M.







No. 148 3-Jaw Self-Centring Chuck
70 mm (2.75") diameter.
Mounted on backplate with
thread suitable for the
nose of the No. 123
Dividing Head.




No. 140 3-Jaw Self-Centring Chuck
63 mm (2.48") diameter.
With collet-type spindle
insert.




No. 149 Face-plate with 4 Tee-
slots. With thread
suitable for the nose
of the No. 123 Dividing
Head.



No. 139 Boring head 24 mm (0.95")
dia. Capacity 0.5 - 30 mm
(0.020" - 1.20")
With collet-type spindle
insert.




No. 124 Dividing plates 90 mm
(3.55") dia. Number of
Notches 0 to 120



No. 141a Cutter Arbor - blank
20 mm dia.x 40 mm long




No. 141b Cutter Arbor - blank
16 mm dia.x 120mm long.




No. 142 Cutter Arbor - short
dia.4 - 5 - 6 - 8 -
10 - 12 - 13 mm or
1/4" - 3/8" - 1/2"



No. 143 Cutter Arbor - long
dia.4 - 5 - 6 - 8 -
10 - 12 - 13 mm or
1/4" - 3/8" - 1/2"



No. 144 Cutter Arbor -
threaded
Thread dia. M 6 - 8 -
10 - 12 or
1/4" - 3/8" - 1/2"



No. 145 Collets
Shank dia. = 12 mm
Capacity = 0-10 mm
Capacity = 0-3/8"



No. 146 Clamping Bolts
Length = 40 mm
= 1.58"
with washer and nut



No. 147 Clamping Piece
Hardened.
Length 40 mm



Armoire
pour
accessoires

Werkzeug-
schränk

Tool
cupboard

