



# **MINI DRILL PRESS**

**MODEL G4014**

## **PARTS LIST**



COPYRIGHT © 1998 BY GRIZZLY INDUSTRIAL, INC.

**WARNING: NO PORTION OF THIS MANUAL MAY BE REPRODUCED IN ANY SHAPE  
OR FORM WITHOUT THE WRITTEN APPROVAL OF GRIZZLY INDUSTRIAL, INC.**

JUNE, 1998 PRINTED IN USA



REF	PART #	DESCRIPTION
01	P4014001	BASE
02	P4014002	COLUMN
03	PB09M	HEX BOLT M8-1.25 X 20
04	P4014004	CLAMPING SLEEVE
05	P4014005	TABLE
06	PB25M	HEX BOLT M12-1.75 X 25
07	P4014007	CLAMPING LEVER
08	P4014008	BODY
09	PSS14M	SET SCREW M8-1.25 X 12
10	PN03M	HEX NUT M8-1.25
11	P4014011	FEED SHAFT
12	P4014012	HANDLE BAR
13	P4014013	KNOB
14	PSS20M	SET SCREW M8-1.25 X 8
15	PW07	SHIFTER BAR
16	PB23	SPRING
17	P4014017	SPRING HOUSING
19	P4014019	JAM NUT M10-1.0
20	PSW06	SWITCH
21	P4014021	MOUNT PLATE
22	P4014022	SHEET METAL SCREW
23	P4014023	GROMET
24	P4014078	POWER CORD
25	P4014025	POINTER
26	P4014019	JAM NUT M10-1.0
28	P4014028	LIMIT BOLT
29	PN01M	HEX NUT M6-1.0
30	P4014030	BRACKET
31	PN06M	HEX NUT M5-0.8
32	P4014032	PHLP HD SCR M5-0.8 X 24
38	P4014038	SPRING
39	P4014039	SLIDE BAR
40	P4014040	RUBBER BUMPER

REF	PART #	DESCRIPTION
41	PB02M	HEX BOLT M6-1.0 X 12
42	PW03M	FLAT WASHER M6
43	P4014043	MOTOR PLATE
44	P4014044	MOTOR
45	P4014045	SPECIAL BOLT
46	P4014046	MOTOR PULLEY
47	PSS04M	SET SCREW M6-1.0 X 12
48	P4014048	PULLEY COVER
49	PW03M	FLAT WASHER M6
50	PS14M	PHLP HD SCR M6-1.0 X 12
51	PVM26	V-BELT M-26 3L260
52	P4014052	SPINDLE PULLEY
53	PSS04M	SET SCREW M6-1.0 X 12
54	PR10M	EXT SNAP RING M22
55	P4014056	SPLINED SLEEVE
56	PR24M	INT SNAP RING M42
57	P6203	BALL BEARING 6203
60	PR03M	EXT SNAP RING M12
62	P6201	BALL BEARING 6201
63	P4014063	RUBBER COLLAR
64	P4014064	QUILL
66	P4014066	SPINDLE
67	P4014067	DRILL CHUCK
68	PS09M	PHLP HD SCR M5-0.8 X 10
69	P4014069	CLAMP
70	PN06M	HEX NUT M5-0.8
71	P4014071	RUBBER WASHER
72	P4014072	SPRING
73	P4014073	SCALE
74	PS08M	PHLP HD SCR M5-0.8 X 12
75	PW02M	FLAT WASHER M5
76	P4014076	SWITCH BOX
77	P4014007	DEGREE SCALE